1987
College 1.2VDC -
20VDC - 2A Power Supply
Modifications:

1989: TO-3 Heatsink added to LM350K REG.
↳: 1/2 A MDL Fuse, due to 1A AGC is wrong!
↳: Replaced burnt-out transformer, bridge rectifier, and LM350k regulator, due to current overload.

9/19/2021: Adjusted Volt Meter and Ammeter. Replaced 120VAC flaky neon bulb for 12VDC Red LED, with 1W 3.3kΩ dropping resistor. Took LED power from raw DC. Repainted cover from Black to Gray.

10/3/2021: Replaced 10kΩ Linear Taper with a 10kΩ, 10-Turn POT. Excellant results!